



DAYCO AFTERMARKET TECHNICAL INFORMATION

Subject:


HAT36 & KTBA218H1

T00007

HONDA HYDRAULIC AUTOMATIC TENSIONER

Engine Codes: Honda Accord J30A1 V6

The cable tie fitted to the tensioner is NOT to be removed until after fitment. Removal of the cable tie before fitment will render the unit inoperable and warranty will be void.



For feedback go to
www.dayco.com.au/feedback

