



## DAYCO AFTERMARKET TECHNICAL INFORMATION

### Subject:

**Drive Belt Tensioner**

**T00015**

**(Hydraulic Actuator Type)**

**Issued Aug15**



This tensioner assembly replacement comes complete with hydraulic actuator and is supplied in a "free" state (i.e. uncompressed).

After fitting the assembly onto the engine, to install the belt use an appropriate socket wrench or ring spanner over the hex nut in the casting to lever over and compress the actuator so as the belt can be placed in position.

### **IMPORTANT NOTE**

Care must be taken to compress the hydraulic actuator slowly, if compressed too quickly it may cause "hydraulic lock" where the actuator cannot be compressed. When further force is applied to overcome this, it may cause the hex to break off the main casting or lead to premature failure of the actuator.

Dayco will not accept any warranty claims for evidence of a broken hex nut off the casting.